How to Determine the Appropriate Wedge for Your Application

- 1. Tape a level to the solid black line.
- 2. Match up which angle looks closest to your situation.
- 3. Fold at that mark and compare against your fascia.
- 4. Try to get the level as close to vertical as possible.
- The angle you choose should be within 3.75° + or of being level.

